Mock Inspection Report

Colorado Springs, CO, USA

Jun 5, 2025

Performed by John Pharris

This is a mock inspection report to demonstrate that the inspector has performed an inspection according to the InterNACHI® Standards of Practice.

Roof

View the InterNACHI® "Roof" inspection standard at https://www.nachi.org/sop.htm#roof.

Items Inspected

Roof-Covering Materials	No Defect(s) Observed
At the time of inspection, roof was observed fron	n the ground level.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Gutters	No Defect(s) Observed
At the time of inspection no defects were obs	served.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301








World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Visit us online at NACHI.ORG

Downspouts


No Defect(s) Observed

At the time of inspection no defects were observed. Recommendation is to have concrete blocks installed to help prevent washout. Home owner is in process of having landscaping installed.






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Vents, Flashing, Skylights, Chimney, and Other Roof Penetrations

No Defect(s) Observed

At the time of inspection no defects were observed.

General Structure of the Roof (from the readily accessible panels, doors or stairs)

No Defect(s) Observed

At the time of inspection no defects were observed.

System Descriptions

pectors 1750 30th St Ste 301 Boulder, CO 80301

The Type of Roof-Covering Materials

Visit us online at NACHI.ORG

- Asphalt Shingle
- At the time of inspection no defects were observed. This is a new home, less than 6 months old, pictures do not show how well the roof looks.



Reported Observations

Did you observe any indications of active roof leaks?

Not Observed

World Headquarters

At the time of inspection no defects were observed.

Exterior

View the InterNACHI® "Exterior" inspection standard at https://www.nachi.org/sop.htm#exterior.

Items Inspected

Exterior Wall-Covering Materials	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Eaves, Soffits and Fascia	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Windows (a representative number)	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Visit us online at **NACHI.ORG**

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

All Exterior Doors

No Defect(s) Observed

At the time of inspection no defects were observed.






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



Flashing and Trim

No Defect(s) Observed

At the time of inspection no defects were observed.

Adjacent Walkways and Driveways	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Stairs, Steps, Stoops, Stairways and Ramps	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







Porches, Patios, Decks, Balconies and Carports	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





Vegetation, Surface Drainage, Retaining Walls and Grading of the Property (where they may adversely affect the structure due to moisture intrusion)

Not Inspected | Not Present

At the time of inspection no landscaping installed: homeowner has a contractor scheduled to install.



System Descriptions

The Type of Exterior Wall-Covering Materials

- Stucco
- Masonry, Brick or Stone
 At the time of inspection no defects were observed.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



Reported Observations

Did you observe any improper spacing between intermediate balusters, spindles or rails?

Not Observed

At the time of inspection no defects were observed.

Visit us online at NACHI.ORG

Basement, Foundation, Crawlspace & Structure

View the InterNACHI® "Basement, Foundation, Crawlspace & Structure" inspection standard at https://www.nachi.org/sop.htm#basement.

Items Inspected

Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Foundation

No Defect(s) Observed

At the time of inspection no defects were observed.







Visit us online at **NACHI.ORG**







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG

At the time of inspection no defects were observed. Basement was finished with a section that was unfinished (storage space) and the utilities were in this location (HVAC, Water Heater, Radon, House cabling).

Crawlspace

Not Inspected | Not Present

Structural Components	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



System Descriptions



Visit us online at NACHI.ORG

The Type of Foundation

• At the time of inspection concrete.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG

The Location of the Access to the Under-Floor Space

• Location is in the basement; unfinished space was present at the time of inspection.



Reported Observations

Did you observe indications of wood in contact with or near soil?

Not Observed

At the time of inspection no defects were observed.

Did you observe ind	lications of active	water penetration?
---------------------	---------------------	--------------------

Not Observed

At the time of inspection no defects were observed.

Did you observe indications of possible foundation movement?

Not Observed

At the time of inspection no defects were observed.

Did you observe cutting, notching or boring of framing members?

Not Observed

At the time of inspection no defects were observed.

Heating

View the InterNACHI $^{\circledR}$ "Heating" inspection standard at https://www.nachi.org/sop.htm#heating.


Items Inspected

Heating System (using normal operating controls)	No Defect(s) Observed
At the time of inspection no defects were observed.	




World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





System Descriptions




At the time of inspection no defects were observed.

Not Observed



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



View the InterNACHI® "Cooling" inspection standard at https://www.nachi.org/sop.htm#cooling.

At the time of inspection no defects were observed.

Items Inspected

Cooling System (using normal operating controls) At the time of inspection no defects were observed. System Descriptions The Location of the Thermostat for the Cooling System See Heating section for location and pictures. The Cooling Method At the time of inspection forced air.	ems mspected
The Location of the Thermostat for the Cooling System • See Heating section for location and pictures. The Cooling Method	Cooling System (using normal operating controls) No Defect(s) Observed
The Location of the Thermostat for the Cooling System • See Heating section for location and pictures. The Cooling Method	At the time of inspection no defects were observed.
See Heating section for location and pictures. The Cooling Method	ystem Descriptions
The Cooling Method	The Location of the Thermostat for the Cooling System
	• See Heating section for location and pictures.
At the time of inspection forced air.	The Cooling Method
	• At the time of inspection forced air.
Reported Observations	eported Observations
Did you observe any cooling system that did not operate? Not Observed	Did you observe any cooling system that did not operate? Not Observed


World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**

Did you observe that the cooling system was inaccessible?

Not Observed

At the time of inspection no defects were observed. (Picture of furnace did not turn out, camera issues)




Plumbing

View the InterNACHI® "Plumbing" inspection standard at https://www.nachi.org/sop.htm#plumbing.

Items Inspected

Main Water Supply Shut-Off Valve

No Defect(s) Observed



Main Fuel Supply Shut-Off Valve	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Water Heating Equipment (including the energy

source, venting connections, emperature/pressure-relief (TPR) valves, Watts	No Defect(s) Observed	
210 valves, and seismic bracing)		
at the time of inspection no defects were observed.		



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







Interior Water Supply (including all fixtures and faucets, by running the water)	No Defect(s) Observed
At the time of inspection no defects were observed.	




World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301






World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



All Toilets (for proper operation by flushing)	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG



All Sinks, Tubs and Showers (for functional drainage)

No Defect(s) Observed

At the time of inspection no defects were observed.

Drain, Waste and Vent System

No Defect(s) Observed

Drainage Sump Pumps (with accessible floats)

Not Inspected Inaccessible

System Descriptions

Whether the Water Supply is Public or Private (based upon observed evidence)

Public supply.

The Location of the Main Water Supply Shut-Off Valve

• Location is in the basement in the unfinished area next to the Hot Water Heater.

The Location of the Main Fuel Supply Shut-Off Valve

• Location is on the exterior of the house on the North-East corner.

The Location of Any Observed Fuel-Storage System

At the time of inspection no fuel-storage systems were observed.

The Capacity of the Water Heating Equipment (if labeled)

• 60 gallons

Reported Observations

Did you observe deficiencies in the water supply?

Not Observed

At the time of inspection no defects were observed.

Did you observe deficiencies in the installation of hot and cold water faucets?

Not Observed

At the time of inspection no defects were observed.

Did you observe active plumbing water leaks?

Not Observed



Not Observed

Did you observe toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate?

Electrical

View the InterNACHI® "Electrical" inspection standard at https://www.nachi.org/sop.htm#electrical.

Items Inspected

Service Drop

No Defect(s) Observed

At the time of inspection no defects were observed. Underground service.

Overhead Service Conductors and Attachment Point

Not Inspected | **Not Present**

At the time of inspection underground service.

Service Head, Gooseneck and Drip Loops

Not Inspected | Not Present

At the time of inspection lines were burred.

Service Mast, Service Conduit and Raceway

No Defect(s) Observed

Electric Meter and Base	No Defect(s) Observed
At the time of inspection no defects were obse	erved.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Service-Entrance Conductors

No Defect(s) Observed







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Visit us online at **NACHI.ORG**

Main Service Disconnect

No Defect(s) Observed



Visit us online at NACHI.ORG

World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Panelboards and Over-Current Protection Devices (circuit breakers and fuses)

No Defect(s) Observed

At the time of inspection no defects were observed.





Service Grounding and Bonding

No Defect(s) Observed

Switches, Lighting Fixtures and Receptacles

No Defect(s) Observed

At the time of inspection no defects were observed.

Ground-Fault Circuit Interrupter Receptacles and Circuit Breakers

No Defect(s) Observed

At the time of inspection no defects were observed. Tested and reset properly.



Visit us offille at NACHI.ORG


Presence of Smoke and Carbon-Monoxide Detectors


No Defect(s) Observed

At the time of inspection no defects were observed. Each bedroom smoke detector was present. Living room with manufactured fireplace a smoke detector was present.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



System Descriptions

The main service disconnect's amperage rating (if labeled)

• At the time of inspection main service was not labeled, panel main disconnect was 200 AMPS

The Type of Wiring Observed

• At the time of inspection 12/3 and 14/3. Home owner had custom electrical wiring installed.

Reported Observations

Did you observe deficiencies in the integrity of the service-entrance conductors' insulation, drip loop, and vertical clearances from grade and roofs?

Not Observed

At the time of inspection no defects were observed.

Did you observe any unused circuit-breaker panel opening that was not filled?

Not Observed

At the time of inspection no defects were observed.

Did you observe the presence of solid conductor aluminum branch-circuit wiring, if readily visible?

Not Observed

At the time of inspection no defects were observed.

Did you observe an issue with any tested receptacle?

Not Observed

At the time of inspection no defects were observed. 124 Volts registered at multiple outlets.

Did you observe the absence of smoke and/or carbon monoxide detectors?

Not Observed

At the time of inspection no defects were observed.



Fireplace

View the InterNACHI® "Fireplace" inspection standard at https://www.nachi.org/sop.htm#fireplace.

Items Inspected

Fireplaces and Chimneys (readily accessible arvisible portions)	No Defect(s) Observed				
At the time of inspection no defects were observed.					
Lintels Above the Fireplace Openings	Not Inspected Inaccessible				
Damper Doors (by opening and closing them, if readily accessible and manually operable)	Not Inspected Inaccessible				
Cleanout Doors and Frames	Not Inspected Not Present				

System Descriptions


1750 30th St Ste 301 Boulder, CO 80301

World Headquarters

Visit us online at NACHI.ORG

The Type of Fireplace

• At the time of inspection manufactured fireplace.



Reported Observations

Did you observe evidence of joint separation, damage or deterioration of the hearth, hearth extension or chambers?

Not Observed



Not Observed

Did you observe manually operated dampers that did not open and close?

Did you observe the lack of a smoke detector in the same room as the fireplace?

Not Observed

Did you observe the lack of a carbon-monoxide detector in the same room as the fireplace?

Not Observed

Did you observe cleanouts not made of metal, pre-cast cement, or other non-combustible material?

Not Observed



Attic, Insulation & Ventilation

View the InterNACHI® "Attic, Insulation & Ventilation" inspection standard at https://www.nachi.org/sop.htm#attic.

Items Inspected

Insulation in Unfinished Spaces (including attics, crawlspaces and foundation areas)

At the time of inspection attic access ladder installed but not completed; Ladder needs to be adjusted to sit on the floor properly.




World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301







World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



Ventilation of Unfinished Spaces (including attics, crawlspaces and foundation areas)

No Defect(s) Observed

At the time of inspection no defects were observed.

Mechanical Exhaust Systems in the Kitchen, Bathrooms and Laundry Area	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at <u>NACHI.ORG</u>





System Descriptions

The Type of Insulation Observed

At the time of inspection batt insulation was observed (unfinished area).

The Approximate Average Depth of Insulation

• At the time of inspection insulation depth was not accessible.

Reported Observations

Did you observe the general absence of insulation or ventilation in unfinished spaces?

Not Observed

At the time of inspection no defects were observed.

Doors, Windows & Interior

View the InterNACHI® "Doors, Windows & Interior" inspection standard at https://www.nachi.org/sop.htm#doors.

Items Inspected

Doors and Windows (a representative number, by opening and closing them)	No Defect(s) Observed
At the time of inspection no defects were observed.	,





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301








World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at **NACHI.ORG**



Floors, Walls and Ceilings

No Defect(s) Observed

At the time of inspection no defects were observed.

Stairs, Steps, Landings, Stairways and Ramps	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Railings, Guards and Handrails	No Defect(s) Observed
At the time of inspection no defects were observed.	




World Headquarters 1750 30th St Ste 301 Boulder, CO 80301



Garage Vehicle Doors	No Defect(s) Observed
At the time of inspection no defects were observed.	



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





System Descriptions

Visit us offille at NACHI.ORG

A Garage Vehicle Door (as manually-operated or installed with a garage door opener)

Instal	led	with a	garage	door	opener	

At the time	of inst	pection	no defects	were observed	l.



World Headquarters 1750 30th St Ste 301 Boulder, CO 80301





Reported Observations

Did you observe improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards or railings?

Not Observed

At the time of inspection no defects were observed. Spindles were horizontal, home owner did question Classic Homes as if that was to local code, and was told that it was not an issue.


World Headquarters 1750 30th St Ste 301 Boulder, CO 80301

Visit us online at NACHI.ORG

Did you observe photo-electric safety sensors that did not operate properly?

Not Observed

At the time of inspection no defects were observed.



Did you observe any window that was obviously fogged or displayed other evidence of broken seals?

Not Observed

At the time of inspection no defects were observed.